18 EXISTING STUCCO SILL PATCH AND REPAIR AS REQUIRED

20 NEW PTD. STEEL WIDEFLANGE LINTEL

23 PTD. SMOOTH STUCCO PILASTER

19 NEW PTD. STEEL PLATE WRAPS/CASING AT NEW BRICK OPENINGS

24 1" INSULATED GLASS IN BLACKENED STEEL FRAME W/ CLEAR SEALER

REPAIR AND REPLACE DAMAGED EXISTING BRICK CORNICE AS REQUIRED

INSULATED GLASS IN BLACKENED STEEL SASH DOOR W/ CLEAR SEALER

25 DASHED LINE DENOTES REMOVE EXISTING MECH EQUIPMENT PATCH REPAIR AND STUCCO TO MATCH

26 EXPOSED HISTORIC PTD. CAST IRON DECORATIVE PILASTER ALTERNATE: POWDER COAT

EXISTING BRICK PATCH AND REPAIR AS REQUIRED REMOVE PAINT CHEMICALLY WITH JASCO PREMIUM PAINT AND EPOXY REMOVER

28 EXISTING CAST IRON LINTEL DEMO TO EXPOSE TO DETERMINE IF SALVAGEABLE. ALTERNATE PTD. 3/8" BENT STEEL PLATE FAUX LINTEL



